

COUNTRY Poland/Czechoslovakia
SUBJECT Czechoslovak Shipyard at Kozle

DATE DISTR.
NO. OF PAGES

PLACE ACQUIRED

25X1

DATE OF INFO.

NO. OF ENCLS.
(LISTED BELOW)

SUPPLEMENT TO
REPORT NO.

25X1

FORN COPY
CIRCULATE

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE
OF THE UNITED STATES WITHIN THE MEANING OF THE ESPIONAGE ACT 50
U.S.C. 31 AND 32, AS AMENDED. ITS TRANSMISSION OR THE REVELATION
OF ITS CONTENTS IN ANY MANNER TO AN UNAUTHORIZED PERSON IS PRO-
HIBITED BY LAW. REPRODUCTION OF THIS DOCUMENT IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION


25X1

1. The Czechoslovak shipyard at the Oder river port of Kozle, Poland, handles minor repairs on Czech tugs and barges. More serious damage which has to be fixed in a drydock is attended to at the Polish shipyard at Rogi, four kilometers downstream from the Czech installation. The tugs OPAVA and VITKOVICE were recently repaired at the Polish yard.

2. The Czechoslovak shipyard is manned by the following staff:

2 Czechoslovaks in the yard office
2 storekeepers
2 carpenters
2 engineers
4 locksmiths
2 welders
1 blacksmith
1 blacksmith's apprentice.

25X1



CLASSIFICATION

CONFIDENTIAL

STATE	<input checked="" type="checkbox"/>	NAVY	<input checked="" type="checkbox"/>	NSRE															
ARMY	<input checked="" type="checkbox"/>	AIR	<input checked="" type="checkbox"/>	FBI															

ILLEGIB

RETURN TO RECORDS CENTER
IMMEDIATELY AFTER USE
JOB 56-377 BOX 31
23792